



Figure 2-19 **Mile 54 Channel Cut**

Between mile 54 and 55, the river channel was straightened during RGCP construction. The site includes extensive ROW on each side of the river. The riparian and upland sites are mowed but provide good opportunities for riparian enhancements.

Integrated USIBWC Land Management Alternative

Point Project Measures	ID	#	Area (ac)
Native vegetation planting	54A	1	19.6

Targeted River Restoration Alternative

Point Project Measures	ID	#	Area (ac)
Open former meander	54C	1	19.6

